

After the 3rd meeting, we decided to have next meeting on 4th of July with something visual. But we didn't hold 4th meeting at on time because Shobha and Michele had GIS lesson. And we postponed meeting on 5th of July and held 4th meeting at on time everybody. June made short presentation about DHI software and he uploaded one short manual (short manual about GIS to MIKE21). And June has stared the MOUSE modeling part.

During meeting, we decided detailed procedures about GIS and software.

- Shobha & Michele : Make something to be displayed like elevation map.

Make M21 bathymetry file, dfs2 file with DEM. And the method is written in our team site document page.

- Ham : Check the calibration stuff like real discharge and water depth.
- June : Upload something about MOUSE.

We will send our short introduction Ham so that Ham can make short introduction page for our team as soon as possible. And next meeting is decided to take place on 11th of July at 11am for June, 5pm for Shobha and Michele, 6pm for Ham.